



NYCT Feasibility Study for ADA Accessibility for Bedford Park Blvd

Work included the design to replace the existing hydraulic elevator which was approaching the end of its useful life. All elevator cabs and equipment within the elevator cabs, shaftways, pits and machinery rooms were to be replaced. Shaftways, pits and machinery rooms are to remain. All elevators meet the guidelines set forth in the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

Location:

Brooklyn, NY

Owner:

NYCT

Services Provided:

Electrical



A.G. CONSULTING ENGINEERING, PC

A.G. Consulting Engineering, PC
131W 33rd Street, 12B
New York, NY 10001
Phone: 212-268-0950
agceng@agceng.com